intertek
Total Quality. Assured.

REPORT NUMBER: SHAT08688724

intertek
Total Quality. Assured.

中国认可
国际互认
检测
TESTING
CNAS L0139

TEST REPORT

Number : SHAT08688724

Applicant : SHANGHAI LANGFENG INDUSTRIAL CO.,LTD
ROOM 905, BULDING 2-T1,JIBEI ROAD 117,
SHANGHAI, CHINA

Attn : YUAN DONGPENG

Date : Mar 04, 2026
THIS IS TO SUPERSEDE REPORT NO. SHAT08685571 DATED MAR 03, 2026

Sample Description As Declared :

No. Of Sample	:	One
Fibre Content	:	-
Material	:	One Pair Of Shoe In Black
Finishing	:	-
End Uses	:	-
Colour	:	Black
Style No.	:	H-9552 IceGrip
Order No./PO No.	:	-
Buyer's Name	:	-
Manufacturer's Name	:	Shanghai Langfeng Industrial Co.,ltd
Ref.	:	-

Applicant's Provided Care Instruction/Label :
-

Date Sample Received	:	Feb 27, 2026
Date Testing Started	:	Feb 27, 2026

Prepared And Checked By:
For Intertek Testing Services Ltd.,Shanghai

Baron Hu
Senior Manager of Footwear Lab

INTERTEK TESTING SERVICES LTD., SHANGHAI
上海天祥质量技术服务有限公司
检验检测专用章
(1)

Intertek Testing Services Ltd., Shanghai
2/F, Building No.4, Shanghai Comalong Technology Service Park,
889 Yishan Road, Shanghai 200233, China
上海天祥质量技术服务有限公司
中国上海宜山路 889 号上海齐来科技服务园区 4 号楼 2 楼 邮编:200233
Tel: +86 21 5339 5999 Fax: +86 21 5426 2030 E-mail: textile.shanghai@intertek.com Website:Intertek.com
Attention is drawn to the terms and conditions printed overleaf

intertek
Total Quality. Assured.

TEST REPORT

Number : SHAT08688724

Tests Conducted (As Requested By The Applicant)

1 Slip Resistance (SATRA TM144: 2021, Ice Surface At -7±2℃, Vertical Force: 500 N):

Smooth Ice(dry):	The 1st Run	
Forepart	0.19	
Heelpart	0.19	
Flat Contact	0.25	

Note:
1. The Outsole Of Test Sample Was Pre-Chilled To -7℃ In Water-Ethanol Bath Before Testing.
2. It Must Be Noted That The Slip Resistance Test Carried Out In This Report Denotes An Indication Of Slip Of This Particular Footwear/Component On The Surface Mentioned In The Test Item. It Is Important To Note That Footwear Is Subject To Many Different Conditions Encountered In Everyday Use And That It Is Impossible To Make Footwear Resistant To Slip In All Conditions. Nevertheless, It Is Generally Accepted That Problems Are Minimized If The Guideline Coefficients Of Friction Are Achieved.

End of Report

Remark: The testing data and result issued by this report is just for scientific research, teaching, internal quality control, product research and development etc. on reference only in the territory of the People's Republic of China.

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

All the tested item are tested under the standard condition (except for indication).

This report shall not be reproduced except in full, without written approval of the laboratory.

Intertek Testing Services Ltd., Shanghai
2/F, Building No.4, Shanghai Comalong Technology Service Park,
889 Yishan Road, Shanghai 200233, China
上海天祥质量技术服务有限公司
中国上海宜山路 889 号上海齐来科技服务园区 4 号楼 2 楼 邮编:200233
Tel: +86 21 5339 5999 Fax: +86 21 5426 2030 E-mail: textile.shanghai@intertek.com Website:Intertek.com
Attention is drawn to the terms and conditions printed overleaf

intertek
Total Quality. Assured.

To : SUIXIAN XUHANG INDUSTRIAL TECHNOLOGY CO.
Attention : YUAN DONGPENG

Date : Mar 04, 2026

Re : Report Revision Notification

Labtest Report Number SHAT08685571 date MAR 03, 2026

Please be informed that all the content recorded in the above captioned report will be void. This captioned report is now superseded by a revised Labtest Report, Number SHAT08688724 , issued on Mar 04, 2026 .

Thank you for your attention

Prepared And Checked By:
For Intertek Testing Services Ltd.,Shanghai

Baron Hu
Senior Manager of Footwear Lab

INTERTEK TESTING SERVICES LTD., SHANGHAI
上海天祥质量技术服务有限公司
检验检测专用章
(1)

safetoe

Intertek Testing Services Ltd., Shanghai
2/F, Building No.4, Shanghai Comalong Technology Service Park,
889 Yishan Road, Shanghai 200233, China
上海天祥质量技术服务有限公司
中国上海宜山路889号上海齐来科技服务园区4号楼2楼 邮编:200233
Tel: +86 21 5339 5999 Fax: +86 21 5426 2030 E-mail: textile.shanghai@intertek.com Website:Intertek.com
Attention is drawn to the terms and conditions printed overleaf